



Chithunzi chitha kukhala choyimira.
Onani malongosoledwe azinthu zazamalonda.

IDT5T995APPGI

Gawo la Nambala: **IDT5T995APPGI**
 Mafotokozedwe Akatundu: IC CLK DRIVER 2.5V PLL 44-TQFP
 Mkhaliidwe wa RoHS: Kutsogolera / RoHS Kumvera
 Datasheets: [IDT5T995APPGI.pdf](#)

Wopanga / Chinthu: **IDT (Integrated Device Technology)**
 Chombo Chochokera: Hong Kong
 Njira Yoperekerana: DHL/Fedex/TNT/UPS/EMS

[TUMIZANI MAFUNSO](#)

Zambiri zamalonda

Gawo la Nambala	IDT5T995APPGI	Wopanga	IDT (Integrated Device Technology)
Kufotokozera	IC CLK DRIVER 2.5V PLL 44-TQFP	Mkhaliidwe Wopanda Ufulu / Mkhaliidwe wa RoHS	Kutsogolera / RoHS Kumvera
Tsamba lazambiri	IDT5T995APPGI.pdf		
Mphamvu - Zopereka	2.3 V ~ 2.7 V	Lembani	PLL Clock Driver
Phukusi la Chipangizo Chothandizira	-	Mndandanda	TurboClock™ II
Kugwirizana - Kulowetsa: Kuchokera	1:8	Kupaka	Tray
Phukusi / Mlanduwu	44-LQFP	PLL	Yes with Bypass
Zotsatira	LVTTTL	Maina Ena	5T995APPGI
Kutantha Kwambiri	-40°C ~ 85°C	Chiwerengero cha maulendo	1
Mtundu Wokwera	Surface Mount	Mphuno Yopanda Chisokonezo (MSL)	3 (168 Hours)
Mkhaliidwe Wopanda Ufulu / Mkhaliidwe wa RoHS	Lead free / RoHS Compliant	Kulowetsa	Clock
Maulendo - Max	200MHz	Kusiyanyitsa / kuonjezera	Yes/Yes
Kusiyanyitsa - Kulowetsa: Kutuluka	No/No	Chigawo Choyambira	IDT5T995

Zamgululi Related

<p>IDT5T9891NLGI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK DRIVER 2.5V PLL 68-VFQFPN Sakanizani: IDT5T9891NLGI8.pdf</p> <p>RFQ</p>	<p>IDT5T995APPGI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK DRIVER 2.5V PLL 44-TQFP Sakanizani: IDT5T995APPGI8.pdf</p> <p>RFQ</p>
<p>IDT5T9891NLGI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK DRIVER 2.5V PLL 68-VFQFPN Sakanizani: IDT5T9891NLGI.pdf</p> <p>RFQ</p>	<p>IDT5T9891NLI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK DRIVER 2.5V PLL 68-VFQFPN Sakanizani: IDT5T9891NLI8.pdf</p> <p>RFQ</p>
<p>IDT5V2305PGI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUFFER 1:5 200MHZ 16TSSOP Sakanizani: IDT5V2305PGI.pdf</p> <p>RFQ</p>	<p>IDT5V2310NRGI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUF 1:10 200MHZ 20VFQFPN Sakanizani: IDT5V2310NRGI.pdf</p> <p>RFQ</p>
<p>IDT5V2310PGI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUF 1:10 200MHZ 24TSSOP Sakanizani: IDT5V2310PGI.pdf</p> <p>RFQ</p>	<p>IDT5T9950APPGI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUFFER/DVR 1:10 32TQFP Sakanizani: IDT5T9950APPGI.pdf</p> <p>RFQ</p>
<p>IDT5T9891NLI Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK DRIVER 2.5V PLL 68-VFQFPN Sakanizani: IDT5T9891NLI.pdf</p> <p>RFQ</p>	<p>IDT5V2310NRGI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUF 1:10 200MHZ 20VFQFPN Sakanizani: IDT5V2310NRGI8.pdf</p> <p>RFQ</p>
<p>IDT5T9950APPGI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUFFER/DVR 1:10 32TQFP Sakanizani: IDT5T9950APPGI8.pdf</p> <p>RFQ</p>	<p>IDT5V2305PGI8 Opanga: IDT (Integrated Device Technology) Kufotokozera: IC CLK BUFFER 1:5 200MHZ 16TSSOP Sakanizani: IDT5V2305PGI8.pdf</p> <p>RFQ</p>

Zogwirizana

IDT (Integrated Device Technology) IDT5T995APPGI	Wopereka IDT5T995APPGI	Wogulitsa IDT5T995APPGI
Mtengo wa IDT5T995APPGI	Zithunzi za IDT5T995APPGI	Chithunzi cha IDT5T995APPGI
Zolemba pa IDT5T995APPGI PDF	IDT5T995APPGI Datasheet Yotsitsa	Masamba IDT5T995APPGI
Msika wa IDT5T995APPGI	Gulani IDT5T995APPGI	Gulani IDT (Integrated Device Technology) IDT5T995APPGI
IDT (Integrated Device Technology) IDT5T995APPGI	Wogulitsa IDT (Integrated Device Technology)	Wopereka IDT (Integrated Device Technology)
IDT (Integrated Device Technology) IDT5T995APPGI	IDT IDT5T995APPGI	IDT (Integrated Device Technology) IDT5T995APPGI
IDT, Integrated Device Technology Inc IDT5T995APPGI	Integrated Device Technology (IDT) IDT5T995APPGI	