



ISL32740EIAZ

Gawo la Nambala: **ISL32740EIAZ**
 Mafotokozedwe Akatundu: ISOLATED, 40MB, IL 3685-1E,1/2 D
 Mkhaliidwe wa RoHS: Kutsogolera / RoHS Kumvera
 Datasheets: [ISL32740EIAZ.pdf](#)

Wopanga / Chinthu: Intersil
 Chombo Chochokera: Hong Kong
 Njira Yoperekerera: DHL/Fedex/TNT/UPS/EMS

[TUMIZANI MAFUNSO](#)

Chithunzi chitha kukhala choyimira.
 Onani malongosoledwe azinthu zazamalonda.

Zambiri zamalonda

Gawo la Nambala	ISL32740EIAZ	Wopanga	Intersil
Kufotokozera	ISOLATED, 40MB, IL 3685-1E,1/2 D	Mkhaliidwe Wopanda Ufulu / Mkhaliidwe wa RoHS	Kutsogolera / RoHS Kumvera
Tsamba lazambiri	ISL32740EIAZ.pdf		
Mphamvu - Zopereka	3 V ~ 5.5 V	Lembani	Transceiver
Phukusi la Chipangizo Chothandizira	16-QSOP	Mndandanda	-
Chikumbumtima Cholondira	28mV	Pulogalamu	RS485
Phukusi / Mlanduwu	16-SSOP (0.154", 3.90mm Width)	Kutentha Kwambiri	-40°C ~ 85°C
Chiwerengero cha madalaivala / opezera	1/1	Mtundu Wokwera	Surface Mount
Mphuno Yopanda Chisokonezo (MSL)	1 (Unlimited)	Nthawi Yotsogolera Yoyenera	17 Weeks
Mkhaliidwe Wopanda Ufulu / Mkhaliidwe wa RoHS	Lead free / RoHS Compliant	Duplex	Half
Kufotokozedwa Kwambiri	1/1 Transceiver Half RS485 16-QSOP	Ndondomeko ya Data	40Mbps

Zamgululi Related

<p>ISL32705EIBZ Opanga: Intersil Kufotokozera: ISOLATED, IL 3022E FULL DUPLEX T Sakanizani: ISL32705EIBZ.pdf</p> <p>RFQ</p>	<p>ISL32740EFBZ-T7A Opanga: Intersil Kufotokozera: TRANSCEIVER DIFF BUS ISOLATED Sakanizani: ISL32740EFBZ-T7A.pdf</p> <p>RFQ</p>
<p>ISL32740EIBZ Opanga: Intersil Kufotokozera: GALVANICALLY ISOLATED, DIFFERENT Sakanizani: ISL32740EIBZ.pdf</p> <p>RFQ</p>	<p>ISL32740EIAZ-T7A Opanga: Intersil Kufotokozera: 40MB HALF DUPLEX TRANSC 16QSOP Sakanizani: ISL32740EIAZ-T7A.pdf</p> <p>RFQ</p>
<p>ISL32704EIBZ-T Opanga: Intersil Kufotokozera: IC TXRX ISOLATED RS485 16SOIC Sakanizani: ISL32704EIBZ-T.pdf</p> <p>RFQ</p>	<p>ISL32704EIBZ-T7A Opanga: Intersil Kufotokozera: IC TXRX ISOLATED RS485 16SOIC Sakanizani: ISL32704EIBZ-T7A.pdf</p> <p>RFQ</p>
<p>ISL32705EIBZ-T Opanga: Intersil Kufotokozera: ISOLATED, IL 3022E FULL DUPLEX T Sakanizani: ISL32705EIBZ-T.pdf</p> <p>RFQ</p>	<p>ISL32740EVAL1Z Opanga: Intersil Kufotokozera: ISL32740 EVAL BOARD 1 - 16 PIN S Sakanizani: ISL32740EVAL1Z.pdf</p> <p>RFQ</p>
<p>ISL32740EVAL2Z Opanga: Intersil Kufotokozera: ISL32740 EVAL BOARD 2 - 16 PIN Q Sakanizani: ISL32740EVAL2Z.pdf</p> <p>RFQ</p>	<p>ISL32740EIAZ-T Opanga: Intersil Kufotokozera: ISOLATED, 40MB, IL 3685-1E HALF Sakanizani: ISL32740EIAZ-T.pdf</p> <p>RFQ</p>
<p>ISL32705EIBZ-T7A Opanga: Intersil Kufotokozera: IC FULL DUPLEX TRANSC 16-PIN Sakanizani: ISL32705EIBZ-T7A.pdf</p> <p>RFQ</p>	<p>ISL32740EIBZ-T Opanga: Intersil Kufotokozera: ISOLATED, 40MB, IL 3685E,1/2 DUP Sakanizani: ISL32740EIBZ-T.pdf</p> <p>RFQ</p>

Zogwirizana

Intersil ISL32740EIAZ
 Mtengo wa ISL32740EIAZ
 Zolemba pa ISL32740EIAZ PDF
 Msika wa ISL32740EIAZ
 Intersil ISL32740EIAZ
 Intersil ISL32740EIAZ

Wopereka ISL32740EIAZ
 Zithunzi za ISL32740EIAZ
 ISL32740EIAZ Datasheet Yotsitsa
 Gulani ISL32740EIAZ
 Wogulitsa Intersil

Wogulitsa ISL32740EIAZ
 Chithunzi cha ISL32740EIAZ
 Masamba ISL32740EIAZ
 Gulani Intersil ISL32740EIAZ
 Wopereka Intersil