



ISL32458EIBZ-T7A

Gawo la Nambala: **ISL32458EIBZ-T7A**

Mafotokozedwe Akatundu: IC TXRX RS422/RS485 8SOIC

Mkhalidwe wa RoHs: Kutsogolera / RoHS Kumvera

Datasheets: [ISL32458EIBZ-T7A.pdf](#)

Wopanga / Chinthu: Intersil

Chombo Chochokera: Hong Kong

Njira Yoperekeru: DHL/Fedex/TNT/UPS/EMS

[TUMIZANI MAFUNSO](#)

Chithunzi chitha kukhala choyimira.
Onani malongosoledwe azinthu zazamalonda.

Zambiri zamalonda

Gawo la Nambala	ISL32458EIBZ-T7A	Wopanga	Intersil
Kufotokozera	IC TXRX RS422/RS485 8SOIC	Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Kutsogolera / RoHS Kumvera
Tsamba lazambiri	ISL32458EIBZ-T7A.pdf		
Mphamvu - Zopereka	3 V ~ 5.5 V	Lembani	Transceiver
Phukusi la Chipangizo Chothandizira	8-SOIC	Mndandanda	-
Chikumbumtima Cholandira	30mV	Pulogalamu	RS422, RS485
Kupaka	Cut Tape (CT)	Phukusi / Mlanduwu	8-SOIC (0.154", 3.90mm Width)
Maina Ena	ISL32458EIBZ-T7ACT	Kutantha Kwambiri	-40°C ~ 85°C
Chiwerengero cha madalaivala / opezera	1/1	Mtundu Wokwera	Surface Mount
Mphuno Yopanda Chisokonezo (MSL)	2 (1 Year)	Nthawi Yotsogolera Yoyenera	6 Weeks
Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Lead free / RoHS Compliant	Duplex	Half
Kufotokozedwa Kwambiri	1/1 Transceiver Half RS422, RS485 8-SOIC	Ndondomeko ya Data	20Mbps

Zamgululi Related

<p>ISL32459EIBZ-T7A Opanga: Intersil Kufotokozera: IC TXRX RS422/RS485 8SOIC Sakanizani: ISL32459EIBZ-T7A.pdf</p> <p>RFQ</p>	<p>ISL32459EIBZ-T Opanga: Intersil Kufotokozera: IC TXRX 5V RS422/485 8SOIC Sakanizani: ISL32459EIBZ-T.pdf</p> <p>RFQ</p>
<p>ISL32470EIBZ-T7A Opanga: Intersil Kufotokozera: IC TXRX RS485 FAULT PROT 14SOIC Sakanizani: ISL32470EIBZ-T7A.pdf</p> <p>RFQ</p>	<p>ISL32457EIBZ-T7A Opanga: Intersil Kufotokozera: IC TXRX RS422/RS485 8SOIC Sakanizani: ISL32457EIBZ-T7A.pdf</p> <p>RFQ</p>
<p>ISL32459EIBZ Opanga: Intersil Kufotokozera: IC TXRX 60V OVP 20V RS485 8SOIC Sakanizani: ISL32459EIBZ.pdf</p> <p>RFQ</p>	<p>ISL32458EIBZ Opanga: Intersil Kufotokozera: IC TXRX 5V RS422/485 8SOIC Sakanizani: ISL32458EIBZ.pdf</p> <p>RFQ</p>
<p>ISL32470EIBZ-T Opanga: Intersil Kufotokozera: IC TXRX RS485 FAULT PROT 14SOIC Sakanizani: ISL32470EIBZ-T.pdf</p> <p>RFQ</p>	<p>ISL32457EIUZ-T Opanga: Intersil Kufotokozera: IC TRANSCEIVER 8-MSOP Sakanizani: ISL32457EIUZ-T.pdf</p> <p>RFQ</p>
<p>ISL32458EIBZ-T Opanga: Intersil Kufotokozera: IC TXRX 5V RS422/485 8SOIC Sakanizani: ISL32458EIBZ-T.pdf</p> <p>RFQ</p>	<p>ISL32470EIBZ Opanga: Intersil Kufotokozera: IC TXRX RS485 FAULT PROT 14SOIC Sakanizani: ISL32470EIBZ.pdf</p> <p>RFQ</p>
<p>ISL32457EIUZ Opanga: Intersil Kufotokozera: IC TXRX RS422/RS485 8MSOP Sakanizani: ISL32457EIUZ.pdf</p> <p>RFQ</p>	<p>ISL32457EIUZ-T7A Opanga: Intersil Kufotokozera: IC TXRX RS422/RS485 8MSOP Sakanizani: ISL32457EIUZ-T7A.pdf</p> <p>RFQ</p>

Zogwirizana

Intersil ISL32458EIBZ-T7A
Mtengo wa ISL32458EIBZ-T7A
Zolemba pa ISL32458EIBZ-T7A PDF
Msika wa ISL32458EIBZ-T7A
Intersil ISL32458EIBZ-T7A
Intersil ISL32458EIBZ-T7A

Wopereka ISL32458EIBZ-T7A
Zithunzi za ISL32458EIBZ-T7A
ISL32458EIBZ-T7A Datasheet Yotsitsa
Gulani ISL32458EIBZ-T7A
Wogulitsa Intersil

Wogulitsa ISL32458EIBZ-T7A
Chithunzi cha ISL32458EIBZ-T7A
Masamba ISL32458EIBZ-T7A
Gulani Intersil ISL32458EIBZ-T7A
Wopereka Intersil