

PL585-P8-0200C

Gawo la Nambala: **PL585-P8-0200C**
 Mafotokozedwe Akatundu: IC CLK BUFFER LVPECL 16TSSOP
 Mkhalidwe wa RoHS: Kutsogolera / RoHS Kumvera
 Datasheets:

Wopanga / Chinthu: N/A
 Chombo Chochokera: Hong Kong
 Njira Yopereker: DHL/Fedex/TNT/UPS/EMS













 **TUMIZANI MAFUNSO** >



Zambiri zamalonda

Gawo la Nambala	PL585-P8-0200C	Wopanga	N/A
Kufotokozera	IC CLK BUFFER LVPECL 16TSSOP	Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Kutsogolera / RoHS Kumvera
Tsamba lazambiri			
Mphamvu - Zopereka	2.97 V ~ 3.63 V	Phukusi la Chipangizo Chothandizira	16-TSSOP
Mndandanda	-	Kugwirizana - Kulowetsa: Kuchokera	1:2
Kupaka	Tube	Phukusi / Mlanduwu	16-TSSOP (0.173", 4.40mm Width)
PLL	Yes	Zotsatira	LVC MOS, LVDS, LVPECL
Kutantha Kwambiri	0°C ~ 70°C	Chiweregero cha maulendo	1
Mtundu Wokwera	Surface Mount	Mphuno Yopanda Chisokonezo (MSL)	1 (Unlimited)
Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Lead free / RoHS Compliant	Kulowetsa	Crystal
Maulendo - Max	800MHz	Kusiyanita / kuonjezera	Yes/Yes
Kusiyanita - Kulowetsa: Kutuluka	No/No	Chigawo Choyambira	PL585

Zamgululi Related

 <p>PL583000XC Opanga: N/A Kufotokozera: IC FANOUT BUFFER 32LQFP</p> <p>RFQ</p>	 <p>PL585-P8-0380C-R Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>
 <p>PL580-390I Opanga: N/A Kufotokozera: IC VCXO 640MHZ 16TSSOP</p> <p>RFQ</p>	 <p>PL585-P8-0200C-R Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>
 <p>PL585-28DC Opanga: N/A Kufotokozera: IC CLOCK BUFFER DIE</p> <p>RFQ</p>	 <p>PL580-390I-R Opanga: N/A Kufotokozera: IC VCXO 640MHZ 16TSSOP</p> <p>RFQ</p>
 <p>PL585-P8-0280C-R Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>	 <p>PL585-P8-0280C Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>
 <p>PL585-P8-0480C Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>	 <p>PL585-88DC Opanga: N/A Kufotokozera: IC CLOCK BUFFER DIE</p> <p>RFQ</p>
 <p>PL580-390I Opanga: N/A Kufotokozera: IC VCXO 640MHZ 16TSSOP</p> <p>RFQ</p>	 <p>PL585-P8-0380C Opanga: N/A Kufotokozera: IC CLK BUFFER LVPECL 16TSSOP</p> <p>RFQ</p>

Zogwirizana

PL585-P8-0200C	Wopereka PL585-P8-0200C	Wogulitsa PL585-P8-0200C
Mtengo wa PL585-P8-0200C	Zithunzi za PL585-P8-0200C	Chithunzi cha PL585-P8-0200C
Zolembe pa PL585-P8-0200C PDF	PL585-P8-0200C Datasheet Yotsitsa	Masamba PL585-P8-0200C
Msika wa PL585-P8-0200C	Gulani PL585-P8-0200C	Gulani PL585-P8-0200C
PL585-P8-0200C	Wogulitsa	Wopereka