

SY100ELT982KG

Gawo la Nambala: **SY100ELT982KG**
 Mafotokozedwe Akatundu: IC TRNLTR UNIDIRECTIONAL 10MSOP
 Mkhalidwe wa RoHS: Kutsogolera / RoHS Kumvera
 Datasheets:

Wopanga / Chinthu: N/A
 Chombo Chochokera: Hong Kong
 Njira Yoperekerera: DHL/Fedex/TNT/UPS/EMS













 **TUMIZANI MAFUNSO** >



Zambiri zamalonda

Gawo la Nambala	SY100ELT982KG	Wopanga	N/A
Kufotokozerera	IC TRNLTR UNIDIRECTIONAL 10MSOP	Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Kutsogolera / RoHS Kumvera
Tsamba lazambiri			
Mtanthauzira Mtundu	Mixed Signal	Phukusi la Chipangizo Chothandizira	10-MSOP
Mndandanda	100ELT	Kupaka	Tube
Phukusi / Mlanduwu	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)	Mtundu Wotsatsa	Differential
Chizindikiro Chotsatira	CML	Maina Ena	1611-SY100ELT982KG
Kutantha Kwambiri	0°C ~ 85°C (TA)	Chiwerengero cha maulendo	1
Mtundu Wokwera	Surface Mount	Mphuno Yopanda Chisokonezo (MSL)	1 (Unlimited)
Mkhalidwe Wopanda Ufulu / Mkhalidwe wa RoHS	Lead free / RoHS Compliant	Chizindikiro cholowera	PECL
Mawonekedwe	-	Kufotokozedwa Kwambiri	Mixed Signal Translator Unidirectional 1 Circuit 1 Channel 1.25Gbps 10-MSOP
Ndondomeko ya Data	1.25Gbps	Zida pa Dera	1
Mtundu wa Channel	Unidirectional		

Zamgululi Related

 <p>SY100EP111UTG-TX Opanga: N/A Kufotokozerera: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>	 <p>SY100ELT982KG-TR Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100ELT28ZG Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100ELT28ZI Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>
 <p>SY100ELT28ZG-TR Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100ELT982KI-TR Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100ELT28ZI-TR Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 8SOIC</p> <p>RFQ</p>	 <p>SY100EP111UTG-TR Opanga: N/A Kufotokozerera: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>
 <p>SY100ELT982KI Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>	 <p>SY100ELT982KC Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>
 <p>SY100EP111UTG Opanga: N/A Kufotokozerera: IC CLK BUFFER 2:10 3GHZ 32TQFP</p> <p>RFQ</p>	 <p>SY100ELT982KC-TR Opanga: N/A Kufotokozerera: IC TRNLTR UNIDIRECTIONAL 10MSOP</p> <p>RFQ</p>

Zogwirizana

SY100ELT982KG	Wopereka SY100ELT982KG	Wogulitsa SY100ELT982KG
Mtengo wa SY100ELT982KG	Zithunzi za SY100ELT982KG	Chithunzi cha SY100ELT982KG
Zolemba pa SY100ELT982KG PDF	SY100ELT982KG Datasheet Yotsitsa	Masamba SY100ELT982KG
Msika wa SY100ELT982KG	Gulani SY100ELT982KG	Gulani SY100ELT982KG
SY100ELT982KG	Wogulitsa	Wopereka